

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

49/06
FEB 28 1994
DIVISION OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/93 To (mo./yr.) 12/93
2. DOGM File Number (Mine No): M 1044/006
3. Mine Name: CLINTON PIT
4. Mineral(s) Mined (or permitted to mine): CLAY
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, ____ 1/4, Section 849, Township 59, Range 12W
____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: INTERPACE Ind. Inc.
8. Permanent Street Address: PO Box 12118
City, State, Zip: OGDEN, UT 84412
Phone: (801) 782-7933
9. Company Representative (or designated operator):
Name: CL PATTERSON
Title: PLANT MANAGER
Business Address: SAME
City, State, Zip: _____
Phone: _____

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 45,000 yards

3. How much **additional acreage** was disturbed during the past year? ± 2.5
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
The North Pit was lengthened & deepened.
ABOUT 50,000 yds OVERBURDEN WAS REMOVED
AND 45,000 yds OF CLAY REMOVED
5. How much acreage was **reclaimed** during the past year? ± 3
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
APPROXIMATELY 40,000 yds FROM NORTH
PIT WAS USED TO BACKFILL LEACH CUT
7. What is the **total disturbed acreage** at years end? ± 22.5
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
PLAN TO MINE ANOTHER 15,000 yds OF CLAY
AND MOVE ANOTHER 20,000 yds OF OVERBURDEN
INTO LEACH CUT AND DO SOME CONTOURING WITH
D-8 CAT

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

C L PATTERSON

Title of Operator:

PLANT MANAGER

Signature of Operator:

C L Patterson

Date:

2/25/94